








Spare Parts / Ersatzteile / Pièces de recharge / Pezzi di Ricambio / Piezas de requesto /
Parte de reposição / Reserveonderdelen / Reservdelar / Reservedeler / Varaosat /
Vraosat / Varahlutir / Ανταλλακτικά / Yedek Parçalar / Náhradní díly / Náhradné diely /
Nadomestni deli / Резервни части / Запчасти / Części Zapasowe / Piese de schimb /
Rendelhető alkatrészek / Запасні частини / Reservni delovi / Резервни делови /
Резервни делови / Atsarginių dalių / Tellitavad varuosad / Rezervju daļu


XX = AA, GN, ..



Pos.	Part No.	
1	A 861 888 XX	
2	A 861 889 XX	
3	A 861 890 XX	
4	A 861 872 NU	
5	A 861 891 XX	
6	A 861 892 NU	
7	A 861 446 NU	
8	A 960 706 NU	
9	A 861 893 NU	
10	A 861 875 NU	
11	A 960 890 NU	
12	A 963 143 NU	
13	A 7851 XX	10mm
	A 7877 XX	20mm
14	A 960 704 NU	20mm
	A 962 476 NU	40mm



Ceratherm T100
A8584..

0326 / A 869 305
Made in Germany





 P	bar	 MAX. 10	 5		Q  (3 bar)
 T	°C	 MAX. 80	 65 55		
					Outlet ↑ 1 2 ↓ 20 18,5 l/min