




Ordering spares / Ersatzteil - Regelung / Pièces de rechange / Parti di ricambio / Lista de recambios / Onderdelen bestellen (NL/B) / Κωδικοί Ανταλλακτικών / Bestilling af reservedele / Beställning av reservdelar / Bestilling av reservedeler / Резервни части / Запчасти / Części zapasowe / Piese de schimb / Rendelhető alkatrészek / Запасні частини / Резервни делови / Резервни делови / Atsarginių dalių / Tellitavad varuosad / Rezerves daļas / Náhradní díly / Náhradné diely / Yedek parça siparişi / Nadomestni deli

XX = AA, AD, ...

- 1 - B 961923 XX
- 2 - A 963751 XX
- 3 - B 961915 XX
- 4 - B 961916 NU
- 5 - B 961920 NU
- 6 - B 961922 NU
- 7 - A 962574 NU
- 8 - B 960255 NU
- 9 - B 961705 AA
- 10 - B 960845 NU

	P	bar		MAX. 10		0,5		MAX. 80		65		40		3,8
	T	°C		1		5		10		1		5		1
	Q	(3 bar)		1		5		10		1		5		1
	I/min	3,8		1		5		10		1		5		1





Ideal Standard









CERAFINE O NUOVO

04.2026 / B565618








B E316 ..



Ideal Standard International NV
Corporate Village – Gent Building
Da Vincilaan 2
1935 Zaventem
Belgium
www.idealstandard.com



8



P	T	°C	4	3	2	1	0
			°C	°C	°C	°C	°C
0,3 MPa 3 bar	50°C	15°C	27	33	41	48	50
	65°C	15°C	33	42	53	63	65
	85°C	15°C	41	53	68	83	85

